

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Wiensberg Cara Compact 640 MEG Pepper
Reg Number - NO GAP	KP24LMP
HPI Clear	Yes
VAT	No
Engine Size	1950
BHP	168
Transmission	Automatic
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	6901
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No


### Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Twin Beds Over Garage, Drop Down Bed
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Alloys, Awning, Electric step, Gaslow, Reversing camera, Satellite dish, Tv Aerial
Decals	Good
Any Damage Found	Yes
Damage Further Info	Small area (1p size) of paint rubbed off on offside below fridge vent




Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Alarm, Auto headlights, Bluetooth, cab A/C, Cab blinds, Cruise control, DAB radio, Habitation A/C, Multifunction steering wheel, Part leather, Sat nav, tracker, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Mark in fabric on drop down bed



### Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No


# CMS MOTORHOME INSPECTION FORM



## Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Full
Service Info	One service invoice 28/01/2026
Cam belt changed	N/A
Habitation service reports	Full
Habitation Info	On same invoice as engine service .28/01/2026





## Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Tim Craner
Sign-off Date	2026-03-12