

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Carado T449
Reg Number - NO GAP	KY16PXP
HPI Clear	Yes
VAT	No
Engine Size	2.3 litre
BHP	130 bhp
Transmission	Manual
Vehicle Weight (kg)	3500 kg
Miles or KM	Miles
Mileage	35987
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	3
Belts	4
Bed Options	Island Bed, Bench Seats
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Awning, Bike Rack, Electric step, Solar panel, Tv Aerial, Alloys, LED daytime running lights
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Small area of damage on NSR corner // Scratches on front bumper



Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	NSF alloy tarnished



Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	cab A/C, Bluetooth, Cab curtains, Carpets, Cruise control, Oven, Tv(s), Upgraded stereo
Other Extras	Second TV
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

### Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Near side locker door soft and rippled
Floor damp/spongy/damaged	No





## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Full
Service Info	Book pictured
Date of Last Engine Service	09/08/2025
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	Last service pictured
Date of Last Habitation Service	03/10/2025



## Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-06-10