

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Bailey Autograph Approach 625
Reg Number - NO GAP	LJ14KTK
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	130
Transmission	Manual
Miles or KM	Miles
Mileage	23417
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No



Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	U Shape Rear
Lounge Layout	U-Shaped Rear Lounge
Layout Correct	Yes
Further Comments	No


CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Bike Rack, Reversing camera, Solar panel, Tv Aerial
Decals	Need attention
Decals Further Info	Overcab decal cracking // O/S decal peeling behind cab // O/S decal on body work is peeling/bobbling



Any Damage Found	Yes
Damage Further Info	Rust on awning end cap // OSR wheel arch needs a new seal // Crack on rear locker door





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Cab blinds, Cruise control, Multifunction steering wheel, Oven, Part leather, Carpets, Other (inc accessories)
Other Extras	2x leisure batteries
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Driver seat has wear and tear // Bin not present on back of door



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	None
Cam belt changed	No
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	L7057
Completed by	Leigh
Sign-off Date	2025-09-22
Price Guide	N/A