

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Swift Bessacarr 584
Reg Number - NO GAP	MK18EWU
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	128
Transmission	Manual
Vehicle Weight (kg)	3850
Miles or KM	Miles
Mileage	12189
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	French Bed
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	LED daytime running lights, Awning, Alloys, Reversing camera, Solar panel, Tv Aerial, Tow bar
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Slight scuff nsr // slight scuff osr bumper //






Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	Slight crazing os front // slight crazing os rear // crazing ns rear // Slight crazing ns front
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Carpets, Cab blinds, Bluetooth, Alarm, Cruise control, DAB radio, Multifunction steering wheel, Heated mirrors, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Upholstery is loose around the corners //



Damp Inspection

Damp (visible/soft)	No
---------------------	----



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Full
Service Info	6 Stamps 04/06/2020 - 03/06/2021 - 07/06/2022 - 07/06/2023 - 23/04/2024 - 17/03/2025
Date of Last Engine Service	17/03/2025
Cam belt changed	Yes
Cam belt info	17/03/2025
Habitation service reports	Partial
Habitation Info	One report 25/04/2025
Date of Last Habitation Service	25/04/2024

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Keenan Parnell
Sign-off Date	2026-06-01