

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Ford Transit Custom
Reg Number - NO GAP	ML700TX
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	170
Transmission	Manual
Miles or KM	Miles
Mileage	29518
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No




Internal Layout

Does internal look original?	Yes
Berths	4
Belts	5
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	No

CMS MOTORHOME INSPECTION FORM


Exterior Inspection

External Extras	Alloys, Front fog lights, LED daytime running lights, Parking sensors, Solar panel
Decals	N/A
Any Damage Found	Yes
Damage Further Info	blister on lower o/s // scratch by drivers door // chip on o/s front bumper corner // small stone chips on bonnet // small dent OSR panel



+2 more photo(s) available

Windscreen	Chip(s) smaller than 10p
------------	--------------------------




Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, Bluetooth, cab A/C, Cruise control, DAB radio, Heated seats, Multifunction steering wheel, Part leather, tracker, Sat nav, Auto headlights
Other Extras	Heated front window screen
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Stickers on fridge door



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	No
Engine Service History	Full
Service Info	Four stamps last one 18-3-25
Cam belt changed	No
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	B5105
Completed by	David Walker
Sign-off Date	2025-09-19
Price Guide	N/A