

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Auto-Trail Mohawk
Reg Number - NO GAP	MX10KLO
HPI Clear	Yes
VAT	No
Engine Size	2300cc
BHP	130bhp
Transmission	Manual
Vehicle Weight (kg)	N/A
Miles or KM	Miles
Mileage	31315
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	6
Belts	4
Bed Options	Bench Seats, Overcab Bed, Twin Beds Over Garage
Lounge Layout	Half Dinette, Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM


Exterior Inspection

External Extras	Alloys, Awning, Electric step, Solar panel, Reversing camera, Tow bar
Decals	Good
Any Damage Found	Yes
Damage Further Info	Near side wing mirror damaged Front lights are heavily fogged Spare wheel cover cracked and damaged Paint peel on bumper



Windscreen	No damage
------------	-----------

Alloy Wheels	Need attention
Alloy Further Info	Near side rear alloy needs refurb




Tyres illegal/cracking/out of date	Yes
Tyre Further Info	N/A
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Cab blinds, Oven, Upgraded stereo
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Shower damaged / inoperable



Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Locker doors into garage rotten at bottom
Floor damp/spongy/damaged	Yes
Floor Info	Both corners of garage soft to the touch at the rear end

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	None
Cam belt changed	No
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-03-26