

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Chausson Flash 28
Reg Number - NO GAP	MX12CCN
HPI Clear	Yes
VAT	No
Engine Size	2.4
BHP	110
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	71508
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	No
Notes	Check for interior damage for changes etc
Berths	3
Belts	4
Bed Options	Island Bed
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	N/A



## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Awning, Habitation door lock, Alloys, Tow bar, Reversing camera, Solar panel, Gaslow, Tv Aerial
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Slight peeling and faded ns // faded os and streaky //



Any Damage Found	Yes
Damage Further Info	Cracked ns front // scratch ns passenger door // broken os rear bumper // cracked os rear bumper //






Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	cab A/C, Multifunction steering wheel, Alarm
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	Yes
Smoking Info	Has a dirty smell too it
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Cupboards been recovered // blind above cab broken // kitchen cupboards re covered // cupboard in bedroom has been recovered //



### Damp Inspection

Damp (visible/soft)	Yes
---------------------	-----

Damp Info	Water staining under ns window // soft under half dinnette
Floor damp/spongy/damaged	No



## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	8 stamps 07/05/2014 - 15/10/2025
Date of Last Engine Service	15/10/2025
Cam belt changed	No
Habitation service reports	None



### Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Keenan Parnell
Sign-off Date	2026-06-05

