

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Autosleeper Nuevo EK
Reg Number - NO GAP	MX18LLJ
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	160
Transmission	Manual
Vehicle Weight (kg)	3650
Miles or KM	Miles
Mileage	24219
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	2
Belts	4
Bed Options	Bench Seats
Lounge Layout	Bench Seats, Two Forward Facing
Layout Correct	No
Further Comments	N/A



## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	LED daytime running lights, Awning, BBQ point, Electric step, Bike Rack, Reversing camera, Solar panel, Tv Aerial, Gaslow, Alloys
Other External Extras	N/A
Decals	Need attention
Decals Further Info	U is missing half the U on the os



Any Damage Found	Yes
Damage Further Info	bush marks ns panel



Windscreen

No damage	
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A



## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Cruise control, Multifunction steering wheel, Part leather, Bluetooth, Heated mirrors, cab A/C, Cab blinds
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	No
Internal Damage	No

### Damp Inspection





Damp (visible/soft)	No
Floor damp/spongy/damaged	Yes
Floor Info	Slightly soft next to fridge



## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	Yes
Engine Service History	Full
Service Info	02/06/2025
Date of Last Engine Service	02/06/2025
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	27/02/2026
Date of Last Habitation Service	27/02/2026



### Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Keenan Parnell

Sign-off Date	2026-05-15