

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Laika Ecovip L3019 Da Vinci Edition
Reg Number - NO GAP	MX72AAO
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	140
Transmission	9 Speed Automatic
Vehicle Weight (kg)	4250
Miles or KM	Miles
Mileage	3634
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Drop Down Bed, Twin Beds Over Garage
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

Vehicle Profile Photos (Front, Rear & Both Sides):





External Extras	Alloys, Awning, BBQ point, Electric step, Gaslow, Reversing camera, Shower point, Solar panel, Tv Aerial
Other External Extras	N/A
Decals	Good
Any Damage Found	No



Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, Bluetooth, cab A/C, Cab blinds, Carpets, Coffee machine, Cruise control, DAB radio, Leather, Multifunction steering wheel, Oven, Sat nav, tracker, Traction control plus, Hill descent control, Tv(s), Upgraded stereo, None
Other Extras	Colour changing light fitted under the drop down bed. Original is present. Controlled via app Original head unit also present. Spare "Non gaslow" gas locker door included
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Slight mark to wood finish on rear bed where infill panel sits




Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No



CMS MOTORHOME INSPECTION FORM









Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	None
Cam belt changed	No
Habitation service reports	Full
Habitation Info	2023,2024,2025
Date of Last Habitation Service	01/10/2025





Test Drive & Sign Off

Test drive - 10 mins

Pass

Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Tim Craner
Sign-off Date	2026-06-19