

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Volkswagen Transporter Conversion
Reg Number - NO GAP	N121DJK
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	180
Transmission	Automatic
Vehicle Weight (kg)	3200
Miles or KM	Miles
Mileage	86810
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	No
More Info	Low coolant
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No







Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Front fog lights, Reversing camera, Parking sensors, Tow bar
Other External Extras	N/A
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Chips n/s front bumper edge // scratch n/s door // scratches and dents n/s rear arch // scratch o/s rear door // bad Rustin o/s rear arch // scratches on o/s side // chip on o/s wing mirror cover







Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	Curbed and front o/s been repainted






Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	Yes
Pop Top Damage Info	Slight marks on o/s side





CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, cab A/C, DAB radio, Diesel heater, Heated mirrors, Leather, Multifunction steering wheel, Upgraded stereo, Oven
Other Extras	N/A
Electrics turn on	No
More Info	Possible leisure battery dead
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Pop top board coming away/torn // drivers bolster starting to crack







Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Invoiced
Date of Last Engine Service	30/11/2020
Cam belt changed	Yes
Cam belt info	Invoiced 20/03/2019
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	Yes
Engine Lights Info	Abs
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	David Walker

Sign-off Date	2026-05-25