

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Toyota Alphard campervan
Reg Number - NO GAP	NH54YBJ
HPI Clear	Yes
VAT	No
Engine Size	2.4
BHP	154
Transmission	Automatic
Vehicle Weight (kg)	2160
Miles or KM	Miles
Mileage	77841
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Mileage Discrepancy
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No


Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Front fog lights, Parking sensors
Other External Extras	N/A
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Damage to fuel filler flap // Mirror missing from rear mount // Slight scuff to OSR bumper corner // Scratches to rear edge of drivers door // Lacquer peel around pop top rim




Windscreen	No damage
Alloy Wheels	

Need attention

Alloy Further Info

All wheels need refurb



Tyres illegal/cracking/out of date

Yes

Tyre Further Info

No date on rear tyres
Front are 2019
All good condition

Electric Step

N/A

Self levelling work

N/A

Pop top canvas damage

Yes

Pop Top Damage Info


Holes in rear of pop top



CMS MOTORHOME INSPECTION FORM









Internal Inspection

Internal Extras	Alarm, cab A/C, Cab curtains, Multifunction steering wheel, Leather, Bluetooth
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Seats are worn



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No



Test Drive & Sign Off

Test drive - 10 mins

Pass

Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Tim Craner
Sign-off Date	2026-06-05