

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Vauxhall Vivaro
Reg Number - NO GAP	NV11DPU
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	113
Transmission	Automatic
Vehicle Weight (kg)	2000
Miles or KM	Miles
Mileage	25072
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No


Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Campervan
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, Tv Aerial
Decals	Good
Any Damage Found	Yes
Damage Further Info	Damage to both sides of rear bumper where tail lift was// Small area of delamination on offside top of rear door// Two scratches on drivers door// All black plastic trim very faded// Tiny dent on offside sliding door






Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	Probably. Only tyre dated is R/O/S which is 2015. All are in good condition
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, cab A/C, DAB radio, Diesel heater, Tv(s), Upgraded stereo
Other Extras	Dash am
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Scuffs to wooden panel inside rear door



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No





CMS MOTORHOME INSPECTION FORM



Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Full
Service Info	Stamps for 2012,2013,2014,2015,2017,2018,2020,,2021,2022,2023,2024 & 2025(2) plus invoice for 2026
Cam belt changed	No
Habitation service reports	None





Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Tim Craner
Sign-off Date	2026-04-15