

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elddis Accordo 105
Reg Number - NO GAP	NX18EBK
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3300
Miles or KM	Miles
Mileage	21676
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Alloys, Tow bar, Reversing camera, Electric step, Tv Aerial, Solar panel
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Small mark on habitation door // Small crack next to OSR light cluster and on OSR corner







Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Cab blinds, Cruise control, Bluetooth, Multifunction steering wheel, Oven, Tv(s), Carpets
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Vinyl lifting on dashboard In places // Light stain on OS bench seat



Damp Inspection

Damp (visible/soft)	No
---------------------	----




CMS MOTORHOME INSPECTION FORM



Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	Four reports: 2019, 2021, 2022, 2023
Date of Last Engine Service	29/03/2023
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	Two reports: 2019 and 2025
Date of Last Habitation Service	25/05/2025





Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Leigh Ireland
Sign-off Date	2026-06-02