

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elddis Accordo 105
Reg Number - NO GAP	AU17AKK
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3300
Miles or KM	Miles
Mileage	19101
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No



Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Reversing camera, Solar panel, Tv Aerial, Habitation door lock
Decals	Good
Any Damage Found	Yes
Damage Further Info	Dent on driver door // Cracks around reversing camera mount // Loose seal NSR lower corner



Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	

Yes

Tyre Further Info

All dated 2016 but all in good condition



Electric Step

N/A

Self levelling work

N/A

Pop top canvas damage

N/A

CMS MOTORHOME INSPECTION FORM


Internal Inspection

Internal Extras	cab A/C, Bluetooth, DAB radio, Cruise control, Carpets, Cab blinds, Cab curtains, Oven, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Stain on OS bench seat



Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Blue staining on either side habitation door and on wall in cupboard next to it
Floor damp/spongy/damaged	No






CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Full
Service Info	Latest: 23/03/2026
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	Latest: 16/03/2026



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Leigh Ireland
Sign-off Date	2026-03-27