

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Rimor Europeo 6
Reg Number - NO GAP	CU07LTT
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	120
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	39283
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	7
Belts	6
Bed Options	Overcab Bed, Bench Seats, Bunk Beds
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A


CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Roof rack, Reversing camera, Ladder, Bike Rack
Decals	Need attention
Decals Further Info	Overcab decal cracking



Any Damage Found	Yes
Damage Further Info	Areas of peel and fading on front end // Rust on wiper arms // NS mirror casing damaged // Scratch on NS // Seal coming away under NS locker // Rust around roofbars // Light damage to NSR corner // Damage to OSR corner // Scuff to OS mirror casing // FIAT badge not present at front










Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	NSR tyres cracking // Both front tyres dated 2012 but good condition







Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, cab A/C, Cab curtains, Climate control, Cruise control, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Vent damage on entrance step // Crack on plastic on overcab



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	No
Engine Service History	None
Cam belt changed	No
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	Yes
V5 tested on DVLA	Yes
Completed by	Leigh Ireland
Sign-off Date	2026-03-24