

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Bilbo's Lezan
Reg Number - NO GAP	GJ07HKB
HPI Clear	Yes
VAT	No
Engine Size	2.5
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	84683
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No



Internal Layout

Does internal look original?	Yes
Berths	2
Belts	4
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Tow bar, Reversing camera
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Paint damage and peel to front bumper and above windscreen// heavy scratch to passenger door // scratches down n/s body // large crack to roof top n/s // paint peel to awning // dent to rear n/s door // damage to o/s bumper and door rear // dent o/s body // cracked roof line fibre glass // both wing mirrors scratched









Windscreen	Chip(s) smaller than 10p
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Heated mirrors, Upgraded stereo, Carpets, Cab curtains
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Rear window delaminated// hab door step broken//



Damp Inspection

Damp (visible/soft)	Yes
---------------------	-----

Yes

Floor Info


Damage to floor



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	26/6/2023
Cam belt changed	N/A
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Rodger Snell
Sign-off Date	2026-03-16