

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Roller-Team Autoroller 746
Reg Number - NO GAP	KS12LUV
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	127
Transmission	Automatic
Vehicle Weight (kg)	3650
Miles or KM	Miles
Mileage	33060
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	6
Belts	6
Bed Options	U Shape Rear, Overcab Bed, Bench Seats
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Awning, Bike Rack, Parking sensors, Reversing camera, Solar panel, Tow bar, Tv Aerial
Decals	Need attention
Decals Further Info	Decals cracked and faded in places



Any Damage Found	Yes
Damage Further Info	Cracked fibreglass above cab n/s // paint peel around hab door //




Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection


Internal Extras	cab A/C, Cruise control, DAB radio, Heated mirrors, Hill descent control, Multifunction steering wheel, Oven, Leather, Traction control plus, Tv(s)
Other Extras	N/A
Electrics turn on	No
More Info	Dead battery
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Kitchen worktop has dent in // leather is cracked // poor reseal around sink bathroom and kitchen unit // unit above cab screwed together





## Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	Yes
Floor Info	No reading but very uneven delaminated




## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	N/A
Cam belt changed	No
Habitation service reports	None



### Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Rodger Snell
Sign-off Date	2026-04-07