

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Autocruise Pioneer Pizarro
Reg Number - NO GAP	KX07FHK
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	120
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	26490
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	No
More Info	Oil slightly over //
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No


Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A


CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Tv Aerial, Electric step, Awning, Parking sensors
Decals	Need attention
Decals Further Info	Slight peeling ns and os overcab and front bonnet



Any Damage Found	Yes
Damage Further Info	Rust under hab door entrance // scuff NSR light cluster // scuffed NSR // gas locker door changed //





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM


Internal Inspection



Internal Extras	cab A/C, Oven, Cruise control, Multifunction steering wheel, Cab blinds
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	No
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Cracked shower tray



Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Soft behind kitchen cupboard // soft behind os bench seat //
Floor damp/spongy/damaged	Yes
Floor Info	Soft under kitchen cupboard // soft under OS bench seat






CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Full
Service Info	17/07/2025
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	25/03/2026



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Keenan Parnell
Sign-off Date	2026-04-06