

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Ace Capri
Reg Number - NO GAP	WA58DZU
HPI Clear	Yes
VAT	No
Engine Size	2200cc
BHP	100 BHP
Transmission	Manual
Vehicle Weight (kg)	3000 kg
Miles or KM	Miles
Mileage	31,005
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No


Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Bike Rack, Electric step, Habitation door lock, Solar panel, Parking sensors, Tv Aerial
Decals	Good
Any Damage Found	Yes
Damage Further Info	Damage to rear bumper Paint peel on bonnet Rusting to top of windscreen Poor seal where reversing camera should fit






Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM


Internal Inspection

Internal Extras	cab A/C, Cab blinds, Carpets, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Area above passenger seat damaged



Damp Inspection





Damp (visible/soft)	Yes
Damp Info	Soft under rear window in kitchen // panel under fly net rotten
Floor damp/spongy/damaged	No



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	13 stamps across 2 books - latest 2021
Cam belt changed	No
Habitation service reports	Full
Habitation Info	Service in 2025



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-03-25