

General Information

Make & Model	Hillside Cromford
Reg Number - NO GAP	PE09UDO
HPI Clear	Yes
VAT	No
Engine Size	1.9
ВНР	101
Transmission	Manual
Miles or KM	Miles
Mileage	52676
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass



Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	No



Exterior Inspection

External Extras	Alloys, Parking sensors, Solar panel
Decals	Need attention
Decals Further Info	OSF decal started to flake



Any Damage Found	Yes
Damage Further Info	Wear to sliding door handle // slight catch to OS of pop top // small areas of peel to front bumper







+1 more photo(s) available

Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	Yes



Internal Inspection

Internal Extras	Oven, Diesel heater
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No



Paperwork

Manuals present	No
Engine Service History	Full
Service Info	Latest 25 // belt done 17 @ 41,000
Cam belt changed	No
Habitation service reports	None







+2 more photo(s) available

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	D4119
Completed by	Andrew Rowe
Sign-off Date	2025-12-01
Price Guide	Off