

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Benimar Mileo 294
Reg Number - NO GAP	PN67NNM
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	147
Transmission	Manual
Miles or KM	Miles
Mileage	15916
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Drop Down Bed, Island Bed
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	No

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Awning, Alloys, Habitation door lock, Reversing camera, Solar panel, Tv Aerial, Air Suspension
Decals	Need attention
Decals Further Info	Fading and cracking



Any Damage Found	Yes
Damage Further Info	O/s wheel arch trim damaged and scratched side skirt




Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Bluetooth, cab A/C, Cab blinds, Carpets, Cruise control, DAB radio, Heated mirrors, Hill descent control, Multifunction steering wheel, Oven, Part leather, Tv(s)
Other Extras	Microwave
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Cab to hab plastic floor trim damaged and rear suspended floor flexing



### Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	2023
Cam belt changed	No
Habitation service reports	None

### Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	L7057
Completed by	Rodger Snell
Sign-off Date	2025-11-24
Price Guide	N/A