

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Auto-Sleepers Symbol
Reg Number - NO GAP	R77PUP
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	101
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	44510
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No



### Internal Layout

Does internal look original?	Yes
Berths	2
Belts	4
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection


External Extras	Awning, Tow bar
Other External Extras	N/A
Decals	Need attention
Decals Further Info	All faded to some degree & minor damage in places





Any Damage Found	Yes
Damage Further Info	Slight rusting on rear wheelarches// Paint peel on both front doors







Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	All 2019. All good condition
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Cab curtains, Carpets, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Cracks in offside upper small window (Declared)



### Damp Inspection

Damp (visible/soft)	No
---------------------	----





## CMS MOTORHOME INSPECTION FORM



### Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	13 stamps in book every year from 2006 -2019 Service records after that have been lost
Date of Last Engine Service	N/A
Cam belt changed	Yes
Cam belt info	08/03/2016 @ 29629 miles
Habitation service reports	None





## Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	Yes
Engine Lights Info	N/A
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Tim Craner
Sign-off Date	2026-05-20