

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	House of Vans Conversion
Reg Number - NO GAP	RJ17WMP
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	130
Transmission	Manual
Miles or KM	Miles
Mileage	64926
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No



Internal Layout

Does internal look original?	Yes
Berths	4
Belts	5
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	No

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Other
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Dent inside passenger door // rust around sliding door handle // rusting on drivers cill // bonnet stone chips




+3 more photo(s) available

Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	Yes

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, DAB radio, Leather, Other (inc accessories)
Other Extras	Microwave
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Sliding door rollers stiff // cover for internal handle on rear door missing // small hole in pop top o/s



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	On line have invoice 8-11-22
Cam belt changed	Yes
Cam belt info	18-3-22
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	D4119
Completed by	David Walker
Sign-off Date	2025-10-10
Price Guide	N/A