

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Compass Avantgarde 200
Reg Number - NO GAP	RV04FUN
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	85
Transmission	Manual
Miles or KM	Miles
Mileage	39015
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	No
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No


Internal Layout

Does internal look original?	Yes
Berths	4
Belts	2
Bed Options	Overcab Bed, U Shape Rear
Lounge Layout	U-Shaped Rear Lounge
Layout Correct	Yes
Further Comments	No

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, Bike Rack, Manual step, Tv Aerial
Decals	Need attention
Decals Further Info	Faded on sides and rear
Any Damage Found	Yes
Damage Further Info	Paint peel on bonnet and wings // chip on n/s arch // small dents on n/s side // rear window cracked top left corner // small dents on rear panel // o/s cill rusting gone into hole // rusting above windscreen
Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	2018



Damp floor underneath	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, Cab curtains, Carpets, Cruise control, Oven, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Bathroom mirror rusting // ceiling mould marks // skylight lug broken // crack on plastic facia to clocks

Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	None
Cam belt changed	Yes
Cam belt info	15-8-25
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
Cruise control comment	N/A
V5 tested on DVLA	No
All stages completed	Yes
Trade plate number	D4119
Completed by	David Walker
Sign-off Date	2025-08-25
Price Guide	N/A