

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Bilbo Celex
Reg Number - NO GAP	SP05DFC
HPI Clear	Yes
VAT	No
Engine Size	2.5
BHP	130
Transmission	Automatic
Vehicle Weight (kg)	3000
Miles or KM	Miles
Mileage	79640
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	5
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM


Exterior Inspection

Vehicle Profile Photos (Front, Rear & Both Sides):







External Extras	Alloys, Parking sensors, Reversing camera
Other External Extras	N/A
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Paint peel on roof and privacy glass on driver side delaminating



Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	All alloys delaminated and chipped





Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Diesel heater, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Mark next to driver sun visor



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No



CMS MOTORHOME INSPECTION FORM





Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Full
Service Info	Major service 26/5/26
Date of Last Engine Service	N/A
Cam belt changed	N/A
Habitation service reports	None





Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Jonathan Hayreh
Sign-off Date	2026-06-23