

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Swift Kon-Tiki 894
Reg Number - NO GAP	SP24YCG
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	160
Transmission	9 Speed Automatic
Vehicle Weight (kg)	5500KG
Miles or KM	Miles
Mileage	4601
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Bench Seats, Island Bed
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Air Suspension, Alloys, Awning, Automatic self levelling, BBQ point, Parking sensors, Reversing camera, Satellite dish, Shower point, Solar panel, Tow bar, LED daytime running lights, Tv Aerial
Decals	Good
Any Damage Found	No
Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	Yes
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Auto wipers, Auto headlights, Bluetooth, cab A/C, Cab blinds, Carpets, Climate control, Cruise control, DAB radio, Habitation A/C, Leather, Hill descent control, Multifunction steering wheel, Oven, Sat nav, Tv(s), Traction control plus
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

### Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No




## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Full
Service Info	Latest pictured
Cam belt changed	N/A
Habitation service reports	Full
Habitation Info	Latest pictured





## Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-04-22