

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Burstner Ixeo Time 586 Sovereign
Reg Number - NO GAP	SP64BJK
HPI Clear	Yes
VAT	No
Engine Size	2.3l
BHP	130 bhp
Transmission	Manual
Vehicle Weight (kg)	3500 kg
Miles or KM	Miles
Mileage	14560
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Bench Seats, Drop Down Bed
Lounge Layout	Half Dinette, Bench Seats, Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, Reversing camera, Solar panel, Satellite dome
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Front off side decals faded / missing



Any Damage Found	No
Windscreen	No damage
Alloy Wheels	Need attention
Alloy Further Info	Alloys badly tarnished





Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Sat nav, Leather, Oven, Cab blinds, cab A/C, Cruise control
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No





CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	Last ticket pictured
Date of Last Engine Service	N/A
Cam belt changed	N/A
Habitation service reports	Full
Habitation Info	Last service pictured
Date of Last Habitation Service	N/A



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-05-26