

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Autocruise Startrail
Reg Number - NO GAP	SR10JVJ
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	29938
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	4
Belts	2
Bed Options	Bench Seats, French Bed
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A


## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Awning, Habitation door lock, Reversing camera, Electric step, Tow bar, Solar panel, Tv Aerial
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Damage to decals



Any Damage Found	Yes
Damage Further Info	Os corner near marker light crack and ns corner crack



Windscreen	Chip(s) smaller than 10p
------------	--------------------------



Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM


### Internal Inspection


Internal Extras	Alarm, cab A/C, Cab blinds, Carpets, Cruise control, Multifunction steering wheel, Tv(s), Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Bench seat has water marks



### Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Soft areas under ns bench seat and ns rear corner in locker , blue stain under ns window
Floor damp/spongy/damaged	Yes
Floor Info	Rear locker and under bench seat ns







## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	No
Engine Service History	Partial
Service Info	Oil service
Date of Last Engine Service	N/A
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	Damp check
Date of Last Habitation Service	N/A



### Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Jonathan Hayreh

Sign-off Date	2026-06-01