

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Honda Elysion Stepwagon Side Conversion
Reg Number - NO GAP	SR54GDJ
HPI Clear	Yes
VAT	No
Engine Size	2.4
BHP	160
Transmission	Automatic
Vehicle Weight (kg)	1850
Miles or KM	Miles
Mileage	83756
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	1
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No


Internal Layout

Does internal look original?	Yes
Berths	4
Belts	2
Bed Options	Campervan
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM


Exterior Inspection

Vehicle Profile Photos (Front, Rear & Both Sides):



External Extras	Alloys, Solar panel, Reversing camera
Other External Extras	N/A
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Odd minor scratches on front & rear bumpers






Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, cab A/C, Cab curtains, Carpets, Cruise control, Diesel heater, Other (inc accessories), Bluetooth, Heated mirrors, Multifunction steering wheel, Sat nav
Other Extras	Electric adjustment on drivers seat
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Scratch on wood on dashboard



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No




CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	Invoices for 2020,2021 & 2024
Date of Last Engine Service	20/03/2024
Cam belt changed	N/A
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
----------------------	------

Yes	
Completed by	Tim Craner
Sign-off Date	2026-07-06