

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Chausson flash 10
Reg Number - NO GAP	WA12CRF
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	125
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	42807
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No



### Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Drop Down Bed
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Front fog lights, Bi-Xenons, Reversing camera, Awning, Tv Aerial, Solar panel
Decals	Good
Any Damage Found	Yes
Damage Further Info	Os front bumper fading // paint peel os front drivers // paint peel osr bumper //



Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM


### Internal Inspection

Internal Extras	cab A/C, Multifunction steering wheel, Cab curtains, Cruise control, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Nice has eaten upholstery //



### Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Water marks os wall into ceiling // os locker door moldy // blue staining behind os bench seats // below os bench seat mold // under kitchen sink blue staining behind//
Floor damp/spongy/damaged	No







## **CMS MOTORHOME INSPECTION FORM**

## Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	12/09/2023
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	02/03/26



## Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No

V5 tested on DVLA	Yes
Completed by	Keenan Parnell
Sign-off Date	2026-03-11