

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Adria Matrix Axess SG590
Reg Number - NO GAP	WA14JJU
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	17104
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Bench Seats, Drop Down Bed
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	N/A


CMS MOTORHOME INSPECTION FORM

Exterior Inspection

Vehicle Profile Photos (Front, Rear & Both Sides):



External Extras	Tv Aerial, Bike Rack, Reversing camera, Awning
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Above cab streaky //



Any Damage Found	Yes
Damage Further Info	Repair front os // repair job nsr bumper corner // slight scuff osr tyre trim //



Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A


CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, cab A/C, Bluetooth, Cab blinds, Carpets, Sat nav, Part leather, Cruise control, DAB radio, Tv(s), Upgraded stereo
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection



Damp (visible/soft)	No
Floor damp/spongy/damaged	Yes
Floor Info	Slightly soft in osr garage corner



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Stamps - 10/03/2019 - 11/02/2020 -2 02/07/2021 - 19/04/2023 - 18/09/2024 - 12/08/2025
Date of Last Engine Service	12/08/2025
Cam belt changed	Yes
Cam belt info	Stamped 10/03/2019
Habitation service reports	Partial
Habitation Info	28/02/2020
Date of Last Habitation Service	28/02/2020



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Keenan Parnell
Sign-off Date	2026-07-07