

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Carado I447 Emotion
Reg Number - NO GAP	WA69AOJ
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3650
Miles or KM	Miles
Mileage	22212
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Drop Down Bed, Twin Beds Over Garage
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	N/A


CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, Bike Rack, Reversing camera, Solar panel, Tv Aerial
Decals	Need attention
Decals Further Info	O/s sun damage



Any Damage Found	Yes
Damage Further Info	Dent behind wheel arch o/s from //light scratches to garage doors o/s body// damage to top n/s corner// dent n/s above water filler




Windscreen	No damage
Alloy Wheels	

Good	
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Cab blinds, Carpets, Cruise control, DAB radio, Heated mirrors, Hill descent control, Traction control plus, Oven, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Unit tape damage in cab area // chip in table top // chip in kitchen work top //



Damp Inspection




Damp (visible/soft)	No
---------------------	----



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	19/1/25
Cam belt changed	Yes
Cam belt info	29/1/25
Habitation service reports	Partial
Habitation Info	22/2/22



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Rodger Snell
Sign-off Date	2026-03-11