

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Toyota vellfire
Reg Number - NO GAP	WU09BCK
HPI Clear	Yes
VAT	No
Engine Size	2.4litre
BHP	168
Transmission	Automatic
Vehicle Weight (kg)	2362
Miles or KM	KM
Mileage	91992
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Campervan
Lounge Layout	Bench Seats, Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Parking sensors, Reversing camera, Tow bar
Other External Extras	N/A
Decals	N/A
Any Damage Found	Yes
Damage Further Info	<p>Scuff on off side front bumper Scratches to off side rear bumper Scuffs to back door Rear roof spoiler badly delaminating Dent to roof Scratch to rear bumper near side Roof badly creased in two places Previous awning brackets have damaged roof Two dents to bonnet Front roof spoiler badly delaminated Front skirt badly scuffed</p>






Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	Yes
Pop Top Damage Info	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Auto headlights, cab A/C, Multifunction steering wheel, Sat nav
Other Extras	N/A
Electrics turn on	No
More Info	Leisure battery useless
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Damage to door trim Poor repair inside trim Damage to flooring



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	No
Engine Service History	None
Cam belt changed	No
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-05-22