

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Chausson flash 610
Reg Number - NO GAP	WU16GOX
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	150
Transmission	Manual
Miles or KM	Miles
Mileage	36483
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Drop Down Bed, Bench Seats
Lounge Layout	Half Dinette, Bench Seats
Layout Correct	Yes
Further Comments	No

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Front fog lights, Awning, Gaslow, Reversing camera, LED daytime running lights
Decals	Need attention
Decals Further Info	N/S decal scuff
Any Damage Found	Yes
Damage Further Info	Bonnet paint chips // scratch os front bumper // tape covering crack above cab // scratches drivers door // scratch hab door // osr cluster and bumper cracked // nsr bumper slight crack // garage rear door handle missing // dent ns panel // ns front panel crazing // O/S and N/S locker door locks need attention



+10 more photo(s) available

Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection


Internal Extras	Bluetooth, Multifunction steering wheel, Part leather, cab A/C, Cruise control
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Upholstery on both cab seats and bench seat worn // ns window blind stuck //



+2 more photo(s) available

Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Soft wall above driver seat
Floor damp/spongy/damaged	No



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Full
Service Info	07/07/25
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	30/04/21



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	K4045
Completed by	Keenan Parnell
Sign-off Date	2025-08-29
Price Guide	N/A