

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Elddis Autoquest 115
Reg Number - NO GAP	WU63OEZ
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	110
Transmission	Manual
Vehicle Weight (kg)	3300
Miles or KM	Miles
Mileage	22458
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No



### Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM



### Exterior Inspection



External Extras	Awning, Gaslow, Tow bar, Reversing camera, Electric step, Solar panel, Tv Aerial
Decals	Good
Any Damage Found	Yes
Damage Further Info	Small dinks on NSR // Scuff on NSR corner pillar // Scuff on O/S behind driver door // OSR behind cassette light crease





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	No dates but all four are perishing





Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A




## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Carpets, Cab curtains, Multifunction steering wheel, Oven, Tv(s)
Other Extras	
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

### Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Blue staining around main skylight
Floor damp/spongy/damaged	Yes
Floor Info	Soft floor at rear







## **CMS MOTORHOME INSPECTION FORM**

# Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	Latest: 02/2024
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	Latest: 2014



# Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	Yes

V5 tested on DVLA	Yes
Completed by	Leigh Ireland
Sign-off Date	2026-03-11