

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Wildax Europa
Reg Number - NO GAP	YJ72CWK
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	140
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	7237
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No


### Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	U Shape Rear
Lounge Layout	U-Shaped Rear Lounge
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Alloys, Awning, BBQ point, LED daytime running lights, Electric step, Parking sensors, Solar panel, Tow bar, Gaslow, Tv Aerial, Reversing camera
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Scratch on n/s side // dent on rear n/s top edge // dent on rear door // dent on o/s side x2 // lower trim o/s come away with lower metal panel pushed in



Windscreen	No damage
Alloy Wheels	Good

Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Bluetooth, cab A/C, Cab blinds, Carpets, Cruise control, DAB radio, Multifunction steering wheel, Oven, Sat nav, Tv(s), tracker
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No


### Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No


## **CMS MOTORHOME INSPECTION FORM**

## Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Full
Service Info	Last one 17-10-25
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	13-8-24



## Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No

V5 tested on DVLA	Yes
Completed by	David Walker
Sign-off Date	2026-03-11