

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	CI Cipro 85 Top Class
Reg Number - NO GAP	YN08NYK
HPI Clear	Yes
VAT	No
Engine Size	2.5
BHP	120
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	47295
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Single Beds
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	N/A


CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Air Suspension, Awning, Reversing camera, Parking sensors, Solar panel, Tv Aerial
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Slightly fading on door //



Any Damage Found	Yes
Damage Further Info	Paint blemishes on bonnet // slight scuff os lower trim // sticker added rear // previous repair job nsr // slight scuff ns // paint flake ns lower trim //







Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A

Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, Carpets, Oven, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Trim on floor is broken // driver and passenger worn //



Damp Inspection



Damp (visible/soft)	Yes
---------------------	-----



CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	One stamp full service 09/11/2022
Date of Last Engine Service	09/11/2022
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	One hab 16/07/2021
Date of Last Habitation Service	16/07/2021



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Keenan Parnell

Sign-off Date	2026-05-29