

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Autocruise Starspirit
Reg Number - NO GAP	YN11AYX
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	128
Transmission	Manual
Miles or KM	Miles
Mileage	38627
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	U Shape Rear
Lounge Layout	U-Shaped Rear Lounge
Layout Correct	Yes
Further Comments	No

## CMS MOTORHOME INSPECTION FORM


### Exterior Inspection

External Extras	Awning, Electric step, Reversing camera, Solar panel, Tv Aerial
Decals	Good
Any Damage Found	Yes
Damage Further Info	N/s paint flakes// awning lock u/s // small dents to n/s // flake to bonnet // fuel filler car clip broken// step to hab damaged



+3 more photo(s) available

Windscreen	Crack
------------	-------



Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	Step is loose
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	cab A/C, Cab blinds, Carpets, Cruise control, Multifunction steering wheel, Oven, Other (inc accessories)
Other Extras	Microwave
Electrics turn on	Yes
Control panel damaged	Yes
More Info	Button damage
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Control panel button



### Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	N/A
Cam belt changed	N/A
Habitation service reports	None



### Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	L7059
Completed by	Rodger Snell
Sign-off Date	2025-09-17
Price Guide	On