

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elddis Autoquest 130
Reg Number - NO GAP	YN560RF
HPI Clear	Yes
VAT	Yes
Engine Size	2.2
BHP	140
Transmission	Manual
Miles or KM	Miles
Mileage	40180
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	5
Belts	4
Bed Options	Bench Seats, Overcab Bed
Lounge Layout	Bench Seats
Layout Correct	No
Further Comments	No

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Electric step, BBQ point, Tv Aerial, Reversing camera
Decals	Good
Any Damage Found	Yes
Damage Further Info	Small dents down NS // small areas of paint peel on front bumper // small hold in Leisure battery locker door // NSR paint around arch bubbling



+4 more photo(s) available

Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Damp floor underneath	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, Carpets, DAB radio, Multifunction steering wheel, Oven, Upgraded stereo, Tv(s), Cab curtains, Alarm
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Additional shelves added in kitchen area // bathroom sink tied up // spray adhesive NS & OS behind cab // damage to entry step taped



+1 more photo(s) available

Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Pimping in OS rear high level cupboard // area of roof slightly swollen // OS overcab wall soft and swollen // NS overcab wall swollen and stained // staining in overcab roof // leisure battery door soft
Floor damp/spongy/damaged	No



+2 more photo(s) available

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	None
Cam belt changed	N/A
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
Cruise control comment	N/A
V5 tested on DVLA	Yes
All stages completed	Yes
Trade plate number	L7060
Completed by	Andrew Rowe
Sign-off Date	2025-09-12
Price Guide	N/A