

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Globecar Vario 499
Reg Number - NO GAP	YN64CDO
HPI Clear	Yes
VAT	No
Engine Size	2.3
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3300
Miles or KM	Miles
Mileage	41378
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	3
Belts	4
Bed Options	Overcab Bed, Bench Seats
Lounge Layout	Half Dinette
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection


External Extras	Electric step
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Peeling on n/s



Any Damage Found	Yes
Damage Further Info	Paint flake on O/s top by hab door // paint flake o/s front h/light and n/s top area // paint flake on bonnet and stone chips // n/s wing mirror broke casing // scratches n/s top side



Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	Yes
Tyre Further Info	2017 front and rears cracking





Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Cruise control, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Hinge on locker below sink broke // marks on over cab ceiling



Damp Inspection

Damp (visible/soft)	Yes
---------------------	-----

No





CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	Four stamps 17, 18, 19, 21
Date of Last Engine Service	04/01/2021
Cam belt changed	Yes
Cam belt info	10/12/19 @ 27728o
Habitation service reports	None



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	David Walker
Sign-off Date	2026-05-29