

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Mclouis Fusion 360
Reg Number - NO GAP	YX23EHK
HPI Clear	Yes
VAT	No
Engine Size	2.2litre
BHP	150 bhp
Transmission	9 Speed Automatic
Vehicle Weight (kg)	3500 kg
Miles or KM	Miles
Mileage	9228
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	N/A
Clutch Slip Test Pass	N/A
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Drop Down Bed, Twin Beds Over Garage
Lounge Layout	Two Forward Facing, Bench Seats
Layout Correct	Yes
Further Comments	N/A


CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Gaslow, Reversing camera, Solar panel, Tv Aerial
Decals	Need attention
Decals Further Info	Edges missing on couple of decals



Any Damage Found	Yes
Damage Further Info	Large stone chips on bonnet Scuff on near side front bumper







Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Bluetooth, cab A/C, Cab blinds, Carpets, Cruise control, DAB radio, Draw locking, Hill descent control, Leather, Multifunction steering wheel, Oven, Sat nav, tracker, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Small Price of veneer missing on bathroom Outer pillar Damage to work surface near hob



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No

CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	None
Cam belt changed	N/A
Habitation service reports	None

Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-04-10