

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elddis Autoquest Prestige 115
Reg Number - NO GAP	CX60AGY
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	100
Transmission	Manual
Vehicle Weight (kg)	3000
Miles or KM	Miles
Mileage	29885
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	No
Notes	Walls painted // bathroom painted and sink changed
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Awning, Electric step, Bike Rack, Tv Aerial
Decals	Good
Any Damage Found	Yes
Damage Further Info	Paint scuffs to bonnet // scattering of dents down NS // dents to rear // tape under windscreen



Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	

No	
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Cab curtains, Diesel heater, Multifunction steering wheel, Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No

Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Staining in o/cab panel // OS high level front cupboard wall swollen // OS wall under window pimpled and stained // NS under bench stained and soft // Back wall in NSR soft // cassette locker door stained & soft
Floor damp/spongy/damaged	No







CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Latest 25
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	Latest 25



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Andrew Rowe
Sign-off Date	2026-02-03