

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Elddis Autoquest 175
Reg Number - NO GAP	FX62CDZ
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	109
Transmission	Manual
Vehicle Weight (kg)	3300
Miles or KM	Miles
Mileage	27874
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, BBQ point, Reversing camera, Solar panel, Tv Aerial, Gaslow, Bike Rack, Electric step, LED daytime running lights
Other External Extras	N/A
Decals	Good
Any Damage Found	Yes
Damage Further Info	Small dink near bike rack







Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	Step is loose
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Alarm, Cab curtains, Cruise control, Carpets, Multifunction steering wheel, Oven, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Shower plastic is damaged // Scuff on plastic on entrance step





Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Blue stain next to front skylight // Pink stain by side of toilet on rear wall
Floor damp/spongy/damaged	No




CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	July 25
Date of Last Engine Service	N/A
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	July 25
Date of Last Habitation Service	N/A



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Jonathan Hayreh

Sign-off Date	2026-04-27