

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Camper King St Tropez
Reg Number - NO GAP	GD22BPE
HPI Clear	Yes
VAT	No
Engine Size	2.0 L
BHP	108 BHP
Transmission	Manual
Vehicle Weight (kg)	2800kg
Miles or KM	Miles
Mileage	32325
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No


Internal Layout

Does internal look original?	Yes
Berths	4
Belts	5
Bed Options	Campervan
Lounge Layout	Two Forward Facing
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Parking sensors, Solar panel, Roof rack
Other External Extras	N/A
Decals	N/A
Any Damage Found	Yes
Damage Further Info	Damaged near side wing mirror Slight scratch on near side front panel Small amount of Craziing and one bubble on rear bumper Scuffs on off side front bumper and off side front wheel arch



Windscreen

No damage	
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	No

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Bluetooth, Leather, Multifunction steering wheel, Cruise control, DAB radio
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Scuff under forward facing bench seats



Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No


CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Full
Service Info	Online history Screenshot of last service
Date of Last Engine Service	N/A
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	Last check pictured
Date of Last Habitation Service	N/A



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-04-27