

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Auto-Sleeper Nuevo ES
Reg Number - NO GAP	MX09ACY
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	33342
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No


Internal Layout


Does internal look original?	Yes
Berths	4
Belts	4
Bed Options	Bench Seats, Overcab Bed
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Electric step, Awning, Other, Reversing camera
Other External Extras	Bike ramp added on the rear //
Decals	Good
Any Damage Found	Yes
Damage Further Info	Paint peel ns front // hab door paint peel and bubbling // nsr and osr bumper scuffed // paint peel drivers door step // bad crazing ns lower trim //









Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	Carpets, Oven, Multifunction steering wheel, Bluetooth, DAB radio
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Trim has tape covering beside bench seats // seal around hab door is loose // mold spots on velvet roof //







Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No





CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	11/03/2024
Date of Last Engine Service	N/A
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	15/04/2024
Date of Last Habitation Service	N/A



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Keenan Parnell
Sign-off Date	2026-04-28