

CMS MOTORHOME INSPECTION FORM

General Information

Make & Model	Devon Limousin
Reg Number - NO GAP	NX09EBV
HPI Clear	Yes
VAT	No
Engine Size	2.5
BHP	100
Transmission	Manual
Vehicle Weight (kg)	3300
Miles or KM	Miles
Mileage	54070
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

Internal Layout

Does internal look original?	Yes
Berths	2
Belts	3
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

CMS MOTORHOME INSPECTION FORM

Exterior Inspection

External Extras	Alloys, Awning, Parking sensors, Solar panel, Tv Aerial, Tow bar
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Faded



Any Damage Found	Yes
Damage Further Info	Windscreen rubber coming away // OSF corner scrape // dent on NSR door // discolouration on NS plastic trim





Windscreen	
------------	--

No damage	
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

CMS MOTORHOME INSPECTION FORM

Internal Inspection

Internal Extras	cab A/C, Carpets
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	Stain on carpet // glue residue on cabinet // holes in cabinet from old mount // roof lining sag // bathroom roof finish cracking





Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Roof lining above side sliding door staining
Floor damp/spongy/damaged	No




CMS MOTORHOME INSPECTION FORM

Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	Aug 24 last
Date of Last Engine Service	N/A
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	Last July 21
Date of Last Habitation Service	N/A



Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	N/A
V5 tested on DVLA	Yes
Completed by	Jonathan Hayreh
Sign-off Date	2026-04-29