

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Bailey Approach 760SE
Reg Number - NO GAP	NX13CEN
HPI Clear	Yes
VAT	No
Engine Size	2.2
BHP	130
Transmission	Manual
Vehicle Weight (kg)	3850
Miles or KM	Miles
Mileage	38564
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	6
Belts	6
Bed Options	Overcab Bed, U Shape Rear, Bench Seats
Lounge Layout	Full Dinette
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Alloys, Awning, Bike Rack, Ladder, Habitation door lock, Reversing camera, Roof rack, Solar panel, Tow bar, Tv Aerial, Gaslow
Decals	Good
Any Damage Found	Yes
Damage Further Info	Scratches o/s front bumper // small amount of trim paint peel n/s lower behind cab //small dent on n/s A POST
Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	N/A
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	cab A/C, Cab blinds, Carpets, Cruise control, DAB radio, Heated mirrors, Multifunction steering wheel, Oven, Part leather, Upgraded stereo, WIFI
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No


### Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	No


## **CMS MOTORHOME INSPECTION FORM**

## Paperwork

Manuals present	Yes
-----------------	-----



Engine Service History	Partial
Service Info	5/4/22
Cam belt changed	N/A
Habitation service reports	Partial
Habitation Info	14/10/19



## Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No

V5 tested on DVLA	Yes
Completed by	Rodger Snell
Sign-off Date	2026-03-13