

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	Autosleeper Broadway EK TB LP
Reg Number - NO GAP	SP21DTO
HPI Clear	Yes
VAT	No
Engine Size	2.0
BHP	140
Transmission	Manual
Vehicle Weight (kg)	3500
Miles or KM	Miles
Mileage	9753
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	2
Belts	2
Bed Options	Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	No

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Alloys, Awning, Bike Rack, BBQ point, Electric step, Reversing camera, Tv Aerial, Gaslow, LED daytime running lights
Decals	Need attention
Decals Further Info	Small area of creased decal to front of offside window



Any Damage Found	Yes
Damage Further Info	3" scratch high up above drivers door



Windscreen	No damage
Alloy Wheels	Good
Tyres illegal/cracking/out of date	No
Electric Step	Fully Working
Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Bluetooth, cab A/C, Cab blinds, Carpets, Cruise control, Multifunction steering wheel, Part leather, Oven, Sat nav, tracker, Tv(s)
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	Yes
Overhead lockers ready	Yes
Internal Damage	No




### Damp Inspection

Damp (visible/soft)	No
Floor damp/spongy/damaged	Yes
Floor Info	2 areas of non visible damp on floor at edges of both bench seats. Not visible or soft

## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	Stamps for 2017,2024,2025 Additional invoice for 2022
Cam belt changed	No
Habitation service reports	Partial
Habitation Info	2022,2024,2025



## Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Tim Craner
Sign-off Date	2026-02-02