

CMS MOTORHOME INSPECTION FORM

General Information

| | |
|------------------------------|----------------------|
| Make & Model | Camperking St Tropez |
| Reg Number - NO GAP | VK70ZY0 |
| HPI Clear | Yes |
| VAT | No |
| Engine Size | 2.0 |
| BHP | 110 |
| Transmission | Manual |
| Vehicle Weight (kg) | N/A |
| Miles or KM | Miles |
| Mileage | 18366 |
| Confirm miles (within 5,000) | Yes |
| Is Mileage Warranted | Yes |
| Engine Keys Count | 2 |
| V5 present | Yes |
| V5 VIN Match | Yes |

Engine Bay

| | |
|---------------------------|------|
| Fluid levels correct? | Yes |
| Oil/Coolant Contamination | No |
| Engine bay check | Pass |


CMS MOTORHOME INSPECTION FORM

Mechanical Inspection

| | |
|----------------------------|-----|
| Brake Pedal Pressure Pass | Yes |
| Handbrake Test Pass | Yes |
| Static Gear Selection Pass | Yes |
| Clutch Slip Test Pass | Yes |
| Steering Noise | No |
| Engine Noise | No |

Internal Layout






| | |
|------------------------------|--------------------|
| Does internal look original? | Yes |
| Berths | 4 |
| Belts | 5 |
| Bed Options | Campervan |
| Lounge Layout | Two Forward Facing |
| Layout Correct | Yes |
| Further Comments | N/A |




CMS MOTORHOME INSPECTION FORM


Exterior Inspection

| | |
|---------------------|--|
| External Extras | Alloys, Awning, Parking sensors |
| Decals | N/A |
| Any Damage Found | Yes |
| Damage Further Info | Some light scratches on N/S // Side bars rusting // Small dink on tailgate |





| | |
|--------------|-----------|
| Windscreen | No damage |
| Alloy Wheels | Good |





| | |
|------------------------------------|-----|
| Tyres illegal/cracking/out of date | No |
| Electric Step | N/A |
| Self levelling work | N/A |
| Pop top canvas damage | Yes |
| Pop Top Damage Info | N/A |

CMS MOTORHOME INSPECTION FORM

Internal Inspection

| | |
|---------------------------|---|
| Internal Extras | Awning (Porch or Safari), Alarm, Bluetooth, cab A/C, Cruise control, DAB radio, Diesel heater, Heated mirrors, Multifunction steering wheel |
| Other Extras | N/A |
| Electrics turn on | Yes |
| Control panel damaged | No |
| Stereo turn on | Yes |
| Smell or signs of smoking | No |
| Cushions correct | Yes |
| Boiler present | Yes |
| Overhead lockers ready | Yes |
| Internal Damage | Yes |
| Damage Info | Pop top tear as above // Seal around hab door damaged // Inner door card on hab door fixings broken |







Damp Inspection

| | |
|---------------------------|----|
| Damp (visible/soft) | No |
| Floor damp/spongy/damaged | No |

CMS MOTORHOME INSPECTION FORM

Paperwork

| | |
|---|---------------|
| Manuals present | Yes |
|  | |
| Engine Service History | Full |
| Service Info | Latest - 2026 |
| Cam belt changed | No |
| Habitation service reports | None |



Test Drive & Sign Off

| | |
|-------------------------------------|------------|
| Test drive - 10 mins | Pass |
| Engine lights | No |
| Dashboard ghosting/Mileage flashing | No |
| V5 tested on DVLA | Yes |
| Completed by | Tim Craner |
| Sign-off Date | 2026-03-16 |