

## CMS MOTORHOME INSPECTION FORM

### General Information

Make & Model	CI Cusona 594
Reg Number - NO GAP	WA56FGK
HPI Clear	Yes
VAT	No
Engine Size	2.0l
BHP	98bhp
Transmission	Manual
Vehicle Weight (kg)	3500kg
Miles or KM	Miles
Mileage	48567
Confirm miles (within 5,000)	Yes
Is Mileage Warranted	Yes
Engine Keys Count	2
V5 present	Yes
V5 VIN Match	Yes

### Engine Bay

Fluid levels correct?	Yes
Oil/Coolant Contamination	No
Engine bay check	Pass

## CMS MOTORHOME INSPECTION FORM

### Mechanical Inspection

Brake Pedal Pressure Pass	Yes
Handbrake Test Pass	Yes
Static Gear Selection Pass	Yes
Clutch Slip Test Pass	Yes
Steering Noise	No
Engine Noise	No

### Internal Layout

Does internal look original?	Yes
Berths	4
Belts	2
Bed Options	Overcab Bed, Bench Seats
Lounge Layout	Bench Seats
Layout Correct	Yes
Further Comments	N/A

## CMS MOTORHOME INSPECTION FORM

### Exterior Inspection

External Extras	Awning, Bike Rack, Manual step, Reversing camera, Solar panel
Other External Extras	N/A
Decals	Need attention
Decals Further Info	Faded but reasonable for age



Any Damage Found	Yes
Damage Further Info	Plastic skirt around vehicle in poor repair Paint peeling around vehicle Crack on back of vehicle Crack on vinyl above drivers door





Windscreen	No damage
Alloy Wheels	N/A
Tyres illegal/cracking/out of date	No
Electric Step	N/A

Self levelling work	N/A
Pop top canvas damage	N/A

## CMS MOTORHOME INSPECTION FORM

### Internal Inspection

Internal Extras	Oven
Other Extras	N/A
Electrics turn on	Yes
Control panel damaged	No
Stereo turn on	Yes
Smell or signs of smoking	No
Cushions correct	Yes
Boiler present	N/A
Overhead lockers ready	Yes
Internal Damage	Yes
Damage Info	One side of overhead cab boarded

### Damp Inspection

Damp (visible/soft)	Yes
Damp Info	Under off side window wall soft with lifting wallpaper Extensive soft flooring under both bench seats Walls soft under both Bench seats All rear wall soft in places with 99% readings all Over
Floor damp/spongy/damaged	Yes
Floor Info	Discussed as above





## CMS MOTORHOME INSPECTION FORM

### Paperwork

Manuals present	Yes
Engine Service History	Partial
Service Info	N/A
Date of Last Engine Service	N/A
Cam belt changed	No
Habitation service reports	None

### Test Drive & Sign Off

Test drive - 10 mins	Pass
Engine lights	No
Dashboard ghosting/Mileage flashing	No
V5 tested on DVLA	Yes
Completed by	Alan Wileman
Sign-off Date	2026-04-24